

FLOORCO TRADING LTD.

TEST REPORT

SCOPE OF WORK

SPC FLOORING

REPORT NUMBER

230804003SHF-011

TEST DATE(S)

2023-08-04 - 2023-08-15

ISSUE DATE


2023-09-04

PAGES

5

DOCUMENT CONTROL NUMBER

LFT-APAC-SHF-OP-10k(September 1, 2022) © 2022 INTERTEK



Intertek Testing Services Shenzhen Ltd. Shanghai Fengxian Branch





Intertek Testing Services Shenzhen Ltd. Shanghai Fengxian Branch
Plant 5, No. 6958 Daye Road, Fengxian District, Shanghai, China
Tel: +86 21-61136116 Fax: 021-61189921

Website: www.intertek.com

Test Report

Statement

- 1. This report is invalid without company's special seal for testing on the assigned page.
- 2. This report is invalid without an authorized person's signature.
- 3. This report is invalid if altered.
- 4.Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Don't copy this report in partial without any official approval in written by our company. This report is invalid without re-stamping the special seal for testing in copying report.
- 5. This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample(s) tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.
- 6.Except for the obligation, responsibility and liability (if any) for the appropriateness and professionality of afore-mentioned testing itself within the scope and amount of the testing fee received, Intertek does not and will not accept any other obligation or liability.
- 7.If the Client has any questions about the test results, Intertek B&C should be informed within the storage period of the samples. The sample storage period ends 5 working days after the offical report issue date. Samples of certification program are retained for the period required by the certification rules. The samples storage period shall be calculated according to the issue date of the original report in the case of quoting results and modifying reports.
- 8.Intertek B&C will service this report for the entire test record retention period. The test record retention period ends 6 years after this report original issue date. The test record retention period for certification program is 10 years. Test records and other pertinent project documentation will be retained for the entire test record retention period.
- 9. The report was digital signed by Shang Hai, Intertek Group plc, please using Adobe Acrobat Reader to verify the authenticity.





Intertek Testing Services Shenzhen Ltd. Shanghai Fengxian Branch Plant 5, No. 6958 Daye Road, Fengxian District, Shanghai, China Tel: +86 21-61136116 Fax: 021-61189921

Website: www.intertek.com

Test Report

Issue Date: 2023-09-04 Intertek Report No. 230804003SHF-011

Applicant: FLOORCO TRADING LTD.

Address: 118 CARBINE ROAD, MT WELLINGTON

Attn: Terry SHI

Test Type: Performance test, samples provided by the applicant.

Product Information

Product Name	SPC FLOORING		Brand	/
Sample		Good Condition	Sample Amount	6pcs
Description		good Condition	Received Date	2023-08-04
Sample ID		Model	Specification	

Test Methods And Standards

Test Standard	EN 438-2:2016+A1:2018, Section 26		
Specification Standard	/		
Test Conclusion	The samples were tested according to the above standards, and the results are shown in the following page.		

Note:

1. This report does not involve sampling. The report only reflects conformity of the tested items of the samples provided by the testing applicant. Representativeness and authenticity of the submitted samples are responsibilities of the testing applicant.

2.Test results were cited from Intertek Report No. 230804003SHF-003

Report Authorized

Name: Sally Xie

Title: Reviewer

oot Engineer

Project Engineer



Test Report

Issue Date: 2023-09-04 Intertek Report No. 230804003SHF-011

Test Items, Method and Results:

Test Item: Resistance to staining

Test Method: EN 438-2:2016+A1:2018, Section 26

Conditioning: Condition the test specimens at $(23 \pm 2)^{\circ}$ C and $(50 \pm 5)\%$ relative humidity for at least 24h

Test Result:

Group	Staining agent	Duration of contact	Result of visual changes
1	Acetone	16 h	5
2	Coffee (approx. 80°C)	16 h	5
3	Sodium hydroxide (25% solution)	10 min	5
3	Hydrogen peroxide (30% solution)	10 min	5
3	Carbon black suspension in paraffin oil	10 min	5

Assessment of results

Numerical rating	Description			
5	No change test area indistinguishable from adjacent surrounding area			
4	Minor change test area distinguishable from adjacent surrounding area, only when the light source is mirrored on the test surface and is reflected towards the observer's eye, e. g. discoloration, change in gloss and colour			
3	Moderate change test area distinguishable from adjacent surrounding area, visible in several viewing directions, e. g. discoloration, change in gloss and colour			
2	Significant change test area clearly distinguishable from adjacent surrounding area, visible in all viewing directions, e. g. discoloration, change in gloss and colour, and/or structure of the surface slightly changed, e.g. cracking, blistering			
1	Strong change the structure of the surface being distinctly changed and/or discoloration, change in gloss and colour, and / or the surface material being totally or partially delaminated			





Test Report

Issue Date: 2023-09-04 Intertek Report No. 230804003SHF-011

Appendix A: Sample Received Photo



Revision:

NO.	Date	Changes
230804003SHF-011	2023-09-04	First issue

